

FILED

JK

NOV 5 1990


OREGON CORNER RESTORATION FORM

Section 35 Township 26S Range 8W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County DOUGLAS Date 3/90

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

CORNER IS A $\frac{5}{8}$ " REBAR SET BY BURT HOLT 0.4 FT ABOVE GROUND IN GOOD CONDITION

16" YEWWOOD N 50° E 15.1 FT. SCRIBING VISIBLE & B.T. TAG

20" HEMLOCK BEARS N 86° W 39.3 FT. SCRIBING VISIBLE & B.T. TAG.

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

PAINTED ALL FACES AND WROT B.T. ON TREE TRUNK OF ALL B.T.'S WITH FLOUR. ORANGE PAINT

Location & Comments

CORNER LIES ON GENTLE S.E. SLOPE IN HEAVY REPROD

Compass Declination 19 1/2°
 Firm/Agency LOVE ROCK TIMBER COMPANY
 Address P.O. BOX 1127 ROSEBURG
 Party Chief KEN HOFFINE
 Notes _____
 Witness GARY ANGBLET

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ken W Hoffine
 OREGON
 JULY 18, 1987
 KEN W. HOFFINE
 2291