

FILED

JK

NOV 5 1990


OREGON CORNER RESTORATION FORM

Section 35 Township 26S Range 8W

County DOUGLAS Date 3/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

CORNER IS A 5/8" REBAR SET BY BURT HOIT IN GOOD CONDITION
30" D.F BEARS S12°E 22.2 FT; GOOD SCAR AND B.T. TAG
8" D.F BEARS S25°W 39.9 FT; GOOD SCAR AND B.T. TAG

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

6" D.F BEARS N67°W 53.4 FT PUT UP A LOW ROCK TIMBER LOCATION TAG
PAINTED FACES AND WROTE B.T. ON TREE TRUNKS OF ALL B.T.'S WITH FLOUR ORANGE PAINT

Location & Comments

CORNER LIES ON 15% SIDESLOPE WITH TIMBER TO THE EAST
 Compass Declination 19 1/2°
 Firm/Agency LOWE ROCK TIMBER
 Address P.O. Box 1127 ROSEBORG
 Party Chief Ken Hoffine
 Notes _____
 Witness GARY ANGIOLLETT

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ken W Hoffine

OREGON
JULY 16, 1987
KEN W. HOFFINE
2291