

FILED

NOV 5 1990


OREGON CORNER RESTORATION FORM

Section 35 Township 26S Range 8W

County Douglas Date 3/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

Ren. # 52 → CORNER IS A BRASS CAP 0.3 FT ABOVE GROUND IN GOOD CONDITION
 12" D.F. BEARS S53°W S. 9 FT.; WELL HEALED FACE AND B.T. TAG
 12" D.F. BEARS N44°E 15.8 FT.; WELL HEALED FACE AND B.T. TAG.

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

PAINTED FACES AND WROTE B.T. ON TREE TRUNKS OF ALL
 B.T.'S WITH FLOUR ORANGE PAINT

Location & Comments

CORNER IS ON STEEP N.W. SIDESLOPE APPROX 250° FT SOUTH OF CREEK ON STEEP SLOPE
 Compass Declination 19 1/2°
 Firm/Agency LOWE ROCK TIMBER COMPANY
 Address P.O. BOX 1127 ROSEBURG
 Party Chief KEN HOFFINE
 Notes _____
 Witness GARY ANGLETT

Surveyor's Seal

