

FILED

JH
MAY 9 1990

**RESTORED CORNER FOR OREGON DEPARTMENT OF FORESTRY COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**

One Quarter corner common to Sections 19 and 20, T.22S., R10W.,
W.M., Douglas county, Oregon.

ORIGINAL: By A. Todd, 1894, contract No. 629

Cross (X) at exact corner point with 1/4 S on West side, this point
falling on a flat rock, 30' x 40' on North slope (cross (X) and 1/4
S missing, sandstone soft and badly decayed. 30' x 40' flat rock
face in place) from which a:

- 4" Chittem bears N 28° E 125 lks.; now 12" badly decayed
chittem on ground with clump of live chittem surrounding
stump hole.
- 8" Fir bears S 80° W 75 lks.; now 30" N 78° W 49.2',
exposed scribes 1/4. Evidence of bearing tree having moved
approximately 3 feet downhill on a steep rock face. I
believe the original bearing of S 80° W should have been
N 80° W.

RESTORED: MAGNETIC VARIATION 19 1/2° EAST

Chiseled 1' x 1' cross (X) at corner point on 30' x 40' rock face,
with 1/4 on West side, and from which a:

- 25" Fir bears N 03° W 15.6 ft. to an aluminum nail in face;
scribed 1/4 S 19 BT.
- 26" Fir bears N 75° E 33.7 ft. to an aluminum nail in face;
scribed 1/4 S 20 BT.
- 26" Fir bears N 21° E 34.0 ft. to an aluminum nail in face;
scribed 1/4 S 20 BT.
- 34" Fir bears N 04° W 29.9 ft. to an aluminum nail in face;
scribed 1/4 S 19 BT.

Set 4"x4"x72" white painted cedar post N 02° E 19.2 ft. from corner
point.

Dated April 25, 1990

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Lloyd D. Smith

OREGON
LLOYD D. SMITH
1101

Present and witnessed by Tim Van Vleet
Eric Urstadt

#106 ✓

C.S. File No. 63/114-1
C