

T

FILED

JK

DEC 12 1990


OREGON CORNER RESTORATION FORM

Section 35 Township 22S Range 5W

County DOUGLAS Date 8/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____


Monument(s) & Accessories Found: (Condition and Source)

CORNER TO A COUNTY BRASS CAP 0.5 FT ABOVE GROUND IN GOOD CONDITION
9" D.F BEARS N88°E 24.0 FT WELL HEALED FACE AND B.T TAG
16" D.F BEARS S18°W 8.4 FT WELL HEALED FACE AND B.T TAG

Ren #74

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

PAINTED FACES AND WROTE B.T. ON TREE TRUNKS OF B.T.'S WITH FLOUR ORANGE PAINT.
PUT LOW ROCK TIMBER LOCATION TAG ON 6" ROUND TREATED FENCE
COURSE BEARING S49°E 1.2 FT.

Location & Comments

NEW FENCE CORNER BEARS Compass Declination 19 1/2°
S49°E 1.2 FT. FENCE Firm/Agency LOW ROCK
RUNS EAST AND SOUTH TIMBER COMPANY
FROM CORNER. CORNER LIES Address P.O. BOX 1127
ON SMALL FLAT BENCH ROSEBURG
ON EAST SLOPE APPROX Party Chief KEN HOFFINE
200 FT. WEST OF SOUTH Notes _____
FLOWING CREEK Witness GARY ANGIOLET

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ken W Hoffine

OREGON
JULY 16, 1987
KEN W. HOFFINE
2291

#1914

C.S. File No. 63/127-2