

FILED

h

DEC 12 1990

OREGON CORNER RESTORATION FORM

Section 24 Township 225 Range 7W

County DOUGLAS Date 5/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

514 | 513

523 | 524

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

Pen #128

CORNER IS A HAINES T-IRON 0.3 FT ABOVE GROUND IN GOOD CONDITION
64" D.F. BEARS N47°E 9.0°E GOOD BARK SCRIBES, TWO B.T. TAGS AND HAINES
BRASS WASHER (ORIG)


21" D.F. BEARS S15°E 12.5 FT WELL HEALED & HEAVILY CHOPPED, WE TAG

15" D.F. BEARS N78°W 24.1 FT WELL HEALED FACE AND B.T. TAG

19" D.F. BEARS S75°W 18.0 FT WELL HEALED FACE AND B.T. TAG

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

PAINTED FACES AND WROTE B.T. ON TREE TRUNKS OF B.T'S
WITH FLOOR ORANGE PAINT.

Location & Comments

CORNER LIES ON VERY
STEEP S.E. SLOPE 3° FT
BELOW 4 TO 6 FT HIGH
ROCK BLUFF AND APPROX
1 CHAIN NORTH OF
DRAW

Compass Declination 19'6"
Firm/Agency LOWE ROCK
TIMBER COMPANY
Address P.O. BOX 1127
ROSEBURG
Party Chief KEN HOFFINE
Notes _____
Witness GARY ANGIOLET

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ken W Hoffine

OREGON
JULY 16, 1987
KEN W. HOFFINE
2291