

FILED

DEC 12 1990

OREGON CORNER RESTORATION FORM

Section 6 Township 23S Range 5W

County DOUGLAS Date 5/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

S32
S6 | S5

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____


Monument(s) & Accessories Found: (Condition and Source)

CORNER IS A BLM ALUMINUM CAP IN GOOD CONDITION
 18" D.F. BEARS S 7 1/2° E 44.2 FT. B.T. TAG
 16" D.F. BEARS S 11° W 33.2 FT. B.T. TAG
 20" D.F. BEARS SOUTH 17 1/2 FT. B.T. TAG
 METAL FENCE POST 1 1/2 FT WEST
 HAINES T-IRON 1.8 FT WEST

1997
 21"
 NO REC.
 NO REC.
 REC # 26
 T23-5

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

PAINTED FACES AND WROTE B.T. ON TREE TRUNKS OF B.T.'S
 WITH FLOUR ORANGE PAINT.

Location & Comments

CORNER LIES ON STEEP
 WEST SLOPE APPROX
 100 FT EAST OF CREEK
 FLOWING NORTH

Compass Declination 19 1/2°
 Firm/Agency LOVE ROCK
TIMBER COMPANY
 Address P.O. BOX 1127

ROSERBURG
 Party Chief KEN LOFFINE
 Notes _____
 Witness _____

Surveyor's Seal
 REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Ken W. Hoffine
 OREGON
 JULY 18, 1987
 KEN W. HOFFINE
 2291

190 T 22-5 X
 # 134 T 23-5 X

C.S. File No. 63/127-11