

FILED

DEC 13 1990

OREGON CORNER RESTORATION FORM

Section 12 Township 23S Range 6W

County DOUGLAS Date 4/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

723 S	
R6W	RSW
S1	SG
S12	S7

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

1943

- ✓ CORNER IS A U.S. GENERAL LAND OFFICE BRASS CAP IN GOOD CONDITION
- ✓ 16" D.F. STUMP S45°W 45.0° FT. SCRIBING VISIBLE (ORIGINAL BT)
- ✓ 38" D.F. BEARS S21°E 31.7 FT. WELL HEALED FACE AND COUNTY B.T. TAG
- ✓ 30" CEDAR BEARS N52°W 47.5 FT. WELL HEALED FACE AND COUNTY B.T. TAG
- ✓ 12" MADRONE BEARS S68°W 19.4 FT. SCRIBING VISIBLE AND COUNTY B.T. TAG
- ✓ 12" D.F. BEARS N56°E 51.2 FT. WELL HEALED FACE AND COUNTY B.T. TAG

Rev #69 T23-6
#103 T23-5

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

PAINTED FACES AND WROTE B.T. ON TREE TRUNK OF B.T.'S WITH FLOUR ORANGE PAINT

Location & Comments

CORNER LIES ON STEEP
 SPUR RIDGE BEARING
 SOUTHWEST

Compass Declination 19 1/2°

Firm/Agency LONG ROCK
TIMBER COMPANY

Address P.O. BOX 1127

ROSEBURG
 Party Chief KEN HOFFINE

Notes _____

Witness GARY ANGIOLET

Surveyor's Seal

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Ken W. Hoffine

OREGON
 JULY 18, 1987
 KEN W. HOFFINE
 2291