

FILED

JK

DEC 17 1990

OREGON CORNER RESTORATION FORM

Section 34 Township 26S Range 8W

County DOUGLAS Date 7/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

1/4 Cor.

S33 | S34

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

✓ CORNER IS A BRASS CAP SET BY SHANER IN GOOD CONDITION
 ✓ 22" D.F. BEARS N 28° E 4.2 FT, SHOWS GOOD SCAR, TWO B.T. TAGS
 ✓ 20" D.F. BEARS N 56° W 11.6 FT, WELL HEALED FACE, AND B.T. TAG

Ren #63

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

PAINTED FACES AND WROTE B.T. ON TREE TRUNKS OF B.T.S WITH FLUOR ORANGE PAINT.

Location & Comments

CORNER LIES ON FLAT
 BENCH APPROX 80 FT
 NORTH OF S.E. FLOODING
 DRAW

Compass Declination 1916
 Firm/Agency LOWE ROCK
TIMBER COMPANY
 Address P.O. BOX 1127

Surveyor's Seal

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Ken W Hoffine

OREGON
 JULY 16, 1987
 KEN W. HOFFINE
 2201

Party Chief KEN HOFFINE
 Notes _____
 Witness GARY ANGIOLLET