

FILED

DEC 20 1990

OREGON CORNER RESTORATION FORM

Section 7 Township 22S Range 7W COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.
County DOUGLAS Date 11/17/90

Corner Designation

SW 1/16 57

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

FD: 3/4 BRASS CAP ON 2" O.D. IRON PIPE, A
D. FIR STUMP BRS. N56W 47.52', A D. FIR
STUMP BRS. S50E 7.59'

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

A 16" D. FIR FACED AND SCRIBED SW 1/16 57 BT
W/TAG BRS. S56W 34.41' TO A SPIKE IN SIDE
CENTER. A 11" D. FIR FACED AND SCRIBED SW 1/16 57 BT
W/TAG BRS. S26E 21.1' TO A SPIKE IN SIDE
CENTER

Location & Comments

CORNER FALLS
20' WEST OF
E OF ROAD

Compass Declination

Firm/Agency STUNTZNER
ENG.

Address PO BOX 118
COOS BAY OR. 97420

Party Chief J. ESTABROOK

Notes

Witness

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Harvey Wilcox
OREGON
JULY 17, 1988
HARVEY WILCOX
2244