

FILED

OREGON CORNER RESTORATION FORM

Section 32 Township 29S Range 7W

MAR 20 1991 JP

County Douglas Date 3-12-91

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

SE 1/16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

Found a wooden 2" x 2" hub at the approximate position of the SE 1/16 corner. It was set by Greg Lang surveying in an unrecorded survey to mark property lines.

Monument Detail

Sketch

Monument Set (Procedures and Description)

Replaced wood hub with a 1" o.d. x 36" iron pipe.

New Accessories

Set 2 reference trees to approximate corner:

15" fir bears N88°W, 8.47' scarred face at breast height. 2 chop marks at base. Tag nailed to tree.

16" fir bears S10°E, 22.18' 2 chop marks at base. Tag nailed to tree.

Location & Comments

Iron pipe set to better perpetuate the approximate position of the SE 1/16 corner. Champion property line posted and flagged to the north and west of corner.

Compass Declination 18°E

Firm/Agency Champion Intl. Corp.

Address P.O. Box 1328
Roseburg, Or. 97470

Party Chief Ron Geisler

Notes _____

Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald G. Geisler

OREGON
JULY 16, 1982
RONALD G. GEISLER
1988