

FILED *sc*

OREGON CORNER RESTORATION FORM

Section 22 Township 30S Range 7W

MAY 11 1993

County DOUGLAS Date 4/27/93

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

21	22
28	27

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

FOUND - BCIP

- FIR, 10", N23 1/2 W, 19.1', SNAG, SCRIBE VISIBLE
- FIR, 22", N58 E, 23.1', SNAG, w/TAG
- FIR, 6", S50 E, 14.2', DOWN-ROTTED
- FIR, 6", S25 1/2 W, 16.8', DOWN-ROTTED
- W. FIR, 14", S57 1/2 E, 28.4', Good Cond, Healed Blazes, w/TAG

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

NEW BTs:

- D. Fir, 14", N64E, 66 3/4', Scribed "S. 22 BT" w/TAG
- D. Fir, 5", S58W, 33 3/4', Scribed "S 28 BT" w/TAG
- PINE, 5", N26W, 36 3/4', Scribed "S 21 BT" w/TAG

Location & Comments

Steel fence posts were set on line from this corner east to the 1/4 22/27

Compass Declination _____

Firm/Agency ROSEBURG

RESOURCES Co.

Address P.O. Box 1088

Roseburg, OR 97470

Party Chief Felix Raddatz

Notes _____

Witness Bill Olson

CORNER LIES 200' SOUTH OF RD #27.0, AND 450' WEST OF RD #28.1

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark F. Smalley
OREGON
JULY 26, 1988
MARK F. SMALLEY
2354

Expires 12/31/94