

R.M. 3-79

FILED JP

SEP 2 1993

OREGON CORNER RESTORATION FORM

Section 16 Township 29S Range 4W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date Aug. 28, 1993

Corner Designation

517 | 516
520 | 521

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

W.H. Wood, Deputy County Surveyor, 1925; Byron, Deputy County Surveyor, 1963; U.S.B.L.M., 1969.

Monument(s) & Accessories Found: (Condition and Source)

Same as Recorded by U.S.B.L.M.

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

None

Compass Declination 20 1/2° E
Firm/Agency Shaner Engineering, Inc.
Address P.O. Box 1430 Roseburg, OR 97470
Party Chief B. Shaner
Notes " "
Witness J. Wright D. Stone

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner

OREGON
OCT. 4, 1987
BRUCE A. SHANER
490

Expires Dec. 31, 1994.

G.S. File No. 63/153-