

FILED JP

OREGON CORNER RESTORATION FORM

Section 27 Township 31S Range 6W

OCT 8 1993

County Douglas Date 9/893

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation

T31S R6W

28/27

33/34

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

Monument(s) & Accessories Found: (Condition and Source)

FOUND 1970 Douglas County Surveyor's BCIP

FOUND 37" DF, N40W, 31<sup>0</sup> feet

FOUND 22" DF, N66W, 28<sup>1</sup> feet, Down

FOUND 40" DF, S80E, 60<sup>0</sup> feet

Monument Detail

Sketch

Monument Set (Procedures and Description)

NONE

New Accessories

SCRIBED 10" D. Fir, S17E, 22<sup>0</sup> feet, "S34 BT"

10" Madrone, N29E, 20<sup>1</sup> feet, "S27 BT"

6" PINE, S28W, 64<sup>1</sup> feet, "S33 BT"

Location & Comments

Corner lies 500 feet  
South of BLM Rd #  
31-6-33.3 in the  
SW corner of a  
unit logged this  
summer.

Compass Declination

Firm/Agency ROSEBURG RESOURCES Co.

Address P.O. Box 1088  
Roseburg, OR 97470

Party Chief Bill Olson

Notes \_\_\_\_\_

Witness Tony Johnson

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 26, 1983  
MARK F. SMALLEY  
2354

*Mark F. Smalley*