

FILED

Date: 8/16/94 By: BC

This survey consists of:

Map \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 63/154

OREGON CORNER RESTORATION FORM

Section 19 Township 29S Range 7W

County Douglas Date 7/8/94

Corner Designation

E 1/16 19/30

DOUGLAS COUNTY  
SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

BLM Survey 1988-1989

Monument(s) & Accessories Found: (Condition and Source)

Iron Pipe & Brass Cap - BLM  
BT: 10" Fir S58°W 66 LKs Partially Healed

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

New BT: 26" Fir N69°W 40<sup>2</sup>' Scribed "E 1/16 BT"

Location & Comments

Surveyor's Seal

Compass Declination 19°

Firm/Agency Roseburg

Forest Products

Address P.O. Box 1088

Roseburg, OR 97470

Party Chief Felix Raddatz

Notes \_\_\_\_\_

Witness \_\_\_\_\_



RENEWS 12/31/94

C.S. File No. 63/154