

FILED

Date: 8/16/94 By: ABC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 63/154

OREGON CORNER RESTORATION FORM

Section 22 Township 31S Range 3W

County Douglas Date 6/1/94

Corner Designation

$\frac{1}{4} \frac{15}{22}$

DOUGLAS COUNTY
SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals/Surveys, etc. R- 148

Monument(s) & Accessories Found: (Condition and Source)

Douglas County Surveyor's Office - Brass Cap w/ Iron Pipe
& orig. Stone

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

SCRIBED 12" MADRONE, NRGE, 35' ft, "1/4 BT"
No other live trees available within 100 feet

Location & Comments

90 feet east of Compass Declination 19°
new road centerline. Firm/Agency ROSEBURG
FOREST PRODUCTS
Area was burned Address P.O. Box 1088
5 or 6 years ago ROSEBURG, OR 97470
Party Chief Bill Olson
Notes Ralph McManis
Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark F. Smalley
OREGON
JULY 26, 1989
MARK F. SMALLEY
2954

Renews 12/31/94

C.S. File No. 63/154