

FILED

Date: 11-14-94 By: JP

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 63/154

OREGON CORNER RESTORATION FORM

Section 36 Township 24S Range 7W

County Douglas Date 10/24/94

DOUGLAS COUNTY  
SURVEYOR

Corner Designation  
Section Corner  
T24S  
35 | 36  
2 | 1  
T25S

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

Monument(s) & Accessories Found: (Condition and Source)

1967 BLM Brass Cap & Iron Pipe

BTs: 43" Fir N50 1/2° W 120<sup>8</sup>' Healed Now 47" (1967 SURVEY)

17" Fir N59° E 8<sup>6</sup>' Healed Now 22" (1967 SURVEY)

25" Fir S16 1/4° E 37<sup>6</sup>' Healed Now 30" (1967 SURVEY)

17" Fir S29 1/2° W 20<sup>8</sup>' Healed Now 24" (1967 SURVEY)

Monument Detail

Sketch

Monument Set (Procedures and Description)

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_


New Accessories

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Location & Comments

Compass Declination \_\_\_\_\_  
 Firm/Agency Roseburg  
Forest Products  
 Address P.O. Box 1088  
Roseburg, Oregon  
 Party Chief F. White  
 Notes W. Olson  
 Witness R. McManis

Surveyor's Seal



C.S. File No. 63/154 (18)