

Retracement of the East boundary of Section 24, Township 28
South, Range 9 West, Willamette Meridian, Coos County, Oregon.

Survey made for the Coos Bay Timber Co. during the period
September 8, 1961 through September 11, 1961.

Fieldwork commenced at the corner for Sections 24 and 25,
T28S. R9W. and Sections 19 and 30, T28S. R8W. Corner post is a $1\frac{1}{4}$
inch galvanized pipe with brass cap set by the Douglas County Sur-
veyor's Office in 1957. There are four new bearing trees for section
corner as follows:

Hemlock 8 inches diameter bearing S79°E 17.1 feet
Hemlock 6 inches diameter bearing S59°W 9.8 feet
Hemlock 36 inches diameter bearing N85°W 21.0 feet
Hemlock 10 inches diameter bearing N46°E 39.3 feet

A random line was run North on a variation of 20° East.

At 2640.0 feet a search was made for the $\frac{1}{4}$ Corner. The bearing trees
could not be found. Random line was then continued North and at 5308
feet the corner to Sections 13, 24, T28S. R9W. and 18 and 19, T28S.
R8W. was found 31.50 feet to the East. The original bearing tree for
Section 19 found which is a 36 inch Douglas fir. A $1\frac{1}{2}$ inch iron pipe
3 feet long was driven 2 feet in ground for section corner post by this
survey.

The bearing and distance of section line is N00° 20' 23"E
5308.10 feet. New bearing trees for the section corner marked as follows:

Hemlock, 16 inches diameter, bearing S19° 45'W 15.8 feet,
scribed S24 BT.

Hemlock, 8 inches diameter, bearing N68° 15'W 15.1 feet,
scribed S13 BT.

Yew, 5 inches diameter, bearing N75° 45'E 12.8 feet scribed
S18 BT.

distances are to center of bearing trees.

Next Page Please

FILED

Date: 2-22-95 By: BC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 63/161

DOUGLAS COUNTY
SURVEYOR

At the position of the $\frac{1}{4}$ Corner Sections 24 and 19, a further search made for original bearing trees. There was no definite evidence found so the $\frac{1}{4}$ Corner Post was set midpoint on true line between section corners.

A $1\frac{1}{2}$ inch iron pipe 3 feet long was driven 2 feet in ground for $\frac{1}{4}$ Corner from which bearing trees were marked as follows:

Hemlock 22 inches bearing East 28.8 feet measured to center of tree and scribed $\frac{1}{4}$ S 19 BT.

Douglas fir stump 48 inches bearing S52°W 25.9 feet measured to nail in face and scribed $\frac{1}{4}$ S 24 BT.

FILED
JAN 4 1962
J. E. LaSalle
COUNTY SURVEYOR

REGISTERED
OREGON
LAND SURVEYOR
John L. Safstrom
MAY 8, 1959
JOHN L. SAFSTROM
477

FILED

Date: 2-22-95 By: BC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 63/161

DOUGLAS COUNTY
SURVEYOR