

M 119-52

FILED

Date: 3/9/95 By: JP
This survey consists of:
Name: M. 119-52
Reference
Corner Plat: CS 63/161

OREGON CORNER RESTORATION FORM

Section 30 Township 30S Range 3W

County Douglas Date Feb. 28, 1995

DOUGLAS COUNTY
SURVEYOR

Corner Designation

SE 1/16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

None.

Monument(s) & Accessories Found: (Condition and Source)

N/A

Monument Detail

Sketch



Monument Set (Procedures and Description)

I set a 3" Brass Cap on a 2 1/2" x 30" Iron Pipe, from which a:

New Accessories

10" D. Fir BT, I scribed "SE 1/16 S30 BT" bears N41°E, 24 1/2 feet.

12" D. Fir BT, I scribed "SE 1/16 S30 BT" bears S34°E, 17 1/2 feet.

6 Foot Steel Fence Post I set, bears North, 20 feet.

Location & Comments

None.

Compass Declination 20°E

Firm/Agency Shaner Engineering, Inc.

Address P.O. Box 1430 Roseburg, Oregon 97470

Party Chief B. Shaner

Notes " "

Witness David Snyder

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A Shaner

OREGON
OCT. 4, 1987
BRUCE A. SHANER
430

Expires June 30, 1996

C.S. File No. 63/161-13