

M 119-52

FILED

Date: 3-9-95 By: JP

This survey consists of:

Map: M 119-52

Name: \_\_\_\_\_

Corner No: C.S. 63/161

OREGON CORNER RESTORATION FORM

Section 30 Township 30S Range 3W

County Douglas Date Feb. 28, '95

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

C<sup>1</sup>/<sub>4</sub> of Sec. 30

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_


Ben Irving set this corner in 1930 and it was recorded as used by Art Evans in 1942 & Art Boyer in 1937.

Monument(s) & Accessories Found: (Condition and Source)

All evidence was gone except the NW Bearing Tree, now a 24" D. Fir Stump with scribes "BT" found and evidence of old BT Face. This BT was N40°W, 122<sup>1</sup>/<sub>2</sub> feet from the corner Irving set, so we replaced corner at proper position from this stump.

Monument Detail

Sketch



Monument Set (Procedures and Description)

I set a 2 1/2" Brass Cap on a 1" x 30" iron pipe, marked as above.

New Accessories

- 10" Cedar BT, I scribed "C<sup>1</sup>/<sub>4</sub> S30 BT" bears N22°E, 70<sup>3</sup>/<sub>4</sub> feet.
- 20" Cottonwood BT, I back scribed "C<sup>1</sup>/<sub>4</sub> S30 BT", bears NB2°W, 6 feet.
- 6 Foot Steel Fence Post, I set, bears North, 1<sup>1</sup>/<sub>2</sub> feet. 12<sup>3</sup>/<sub>4</sub> feet.
- 6 Foot Steel Fence Post, " ", bears West, 1<sup>1</sup>/<sub>2</sub> feet.

Location & Comments

Corner is on North Bank of a meander channel of S. Umpqua River. & Corner is S45°E, 60 feet from S. shoulder paved, Tiller-Trail Highway.

Compass Declination 20°E  
 Firm/Agency Shaner Engineering, Inc.  
 Address P.O. Box 1430 Roseburg, OR 97470  
 Party Chief B. Shaner  
 Notes " "  
 Witness David Snyder

Surveyor's Seal

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

Bruce A Shaner

OREGON  
 OCT. 4, 1987  
 BRUCE A. SHANER  
 430

Expires June 30, 1996.

C.S. File No. 63/161-17

\* Notify County Road Dept. of this new corner. They will rebuild highway soon. BS