

FILED

Date: 3/13/95 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 63/161-20

March 1, 1995

Janet Lundeen
Douglas County Surveyor
Rm 205 Justice Building
Roseburg, OR 97470


DOUGLAS COUNTY
SURVEYOR

Dear Janet:

As per your request for information regarding the east one-quarter corner of section 10, T24S, R6W. I have found in our files that in April 1973, a Roseburg Lumber Company survey crew subdivided the section using a staff compass and steel tape. An 1 1/2" iron rod was set for the east one-quarter corner. Its position was computed by single proportion, and was later accepted by the BLM(pg 15241).

Also set for this survey were 1 1/2" iron pipes for the N 1/16 and the S 1/16 between sections 10 and 11, the C 1/4 of section 10, and S 1/16 between sections 9 and 10. A fence post was set for the SW 1/16 corner and the W 1/16 between sections 10 and 15 were marked with wood stakes.

I have enclosed a diagram that was draw on the cover of the traverse notes. Please give me a call if you have any questions.

Sincerely,
ROSEBURG FOREST PRODUCTS

Mark F. Smalley
Land Surveyor LS 2354

C.S. File No. 63/161-20

