

FILED

Date: 7-19-95 By: JP

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: C.S. 63/161-29

OREGON CORNER RESTORATION FORM

Section 30 Township 23S Range 9W

County DOUGLAS Date 6-27-95

DOUGLAS COUNTY
SURVEYOR

Corner Designation

C 1/4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. M113-348

99

Monument(s) & Accessories Found: (Condition and Source)

- 2 1/2" BRASS CAP
- 11" FIR N49W, 8 3/4
- 13" FIR N21E, 10 6/8
- 11" FIR S08E, 27 8/8
- 9" FIR S24W, 24 3/8
- ALL BT'S BLAZED & SCRIBED "C 1/4 S30BT" IN M113-348

Monument Detail

Sketch

C 1/4 • S30

LS1091
1991

Monument Set (Procedures and Description)

New Accessories

Location & Comments

CORNER LIES ON
A SOUTHEAST SLOPE
& CUTTING CORNER

Compass Declination 19 1/2°

Firm/Agency WARD NORTHWEST
INC.

Address P.O. Box 105
FLORENCE, OR 97439

Party Chief WAYNE R. DONOVAN

Notes _____

Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Wayne R. Donovan

OREGON
JULY 21, 1992
WAYNE R. DONOVAN
2553

EXP. 12/31/95

C.S. File No. 63/161-29

102
C 1/4