

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 255 Range 7W Sec. 9 County DOUGLAS

State OR Date 12/04/89 No. _____

DEC 15 1989

Corner Designation _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

$\frac{1}{4} \frac{S9}{S16}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #31 #55-A, 1985 BLM SURVEY

Monument(s) Found: (Condition and Source)

A 2 1/2" DIA DCSO BRASS CAP ON AN IRON PIPE, FLUSH WITH GROUND (FROM REN #55A)

COUNTY SURVEYORS OFFICE

$\frac{1}{4} \frac{S9}{S16}$

T255 R7W

1959

Accessories Found:

12" NOW 20" DIA. 2 1/2 FT HIGH ROTTED D. FIR STUMP, WITH SCRIBING "BT" FOUND ON A PREVIOUSLY OPENED BLAZE, BEARS S 25 1/2° W, 23.4 FT. (AGREES WITH MOST RECENT RENEWALS) ORIG-BT

13" NOW 10" DIA. BROKEN AND ROTTED CHINQUIDIN STUMP, NO SCRIBING OR BLAZES VISIBLE, BEARS N 43 1/2° W, 55.8 FT (AGREES WITH RECORD). FROM REN #55-A

12" NOW 3 1/2" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE, BEARS S 83° E, 75.5 FT (AGREES WITH RECORD) FROM REN #55-A

13" NOW 29" DIA. D. FIR, PREVIOUSLY OPENED ON SOUTH SIDE IN REN #55-A AND SCRIBING AXED OUT, THIS BT WENT TO AN ERRONEOUS CORNER SET BY KERR IN REN #31, NO BLAZES FOUND FACING 1959 DCSO CORNER. TREE BEARS N 64 1/2° W, 13.9 FT WITH AGREES 1985 BLM SURVEY RECORD.

#141 X

C.S. File No. 64/3-11

C

