

*JH*

GOVERNMENT CORNER RESTORATION FORM

Township 265 Range 7W Sec. 3 County DOUGLAS

FEB 13 1990

State OREGON Date 9/26/88 No. \_\_\_\_\_

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation \_\_\_\_\_

$\frac{1}{4} \frac{S3}{S10}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #24

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

AT THE REQUEST OF THE PROPERTY OWNER TO THE NORTH A SEARCH FOR ORIGINAL AND RENEWAL #24 MONUMENTS WAS MADE; NO EVIDENCE WAS FOUND.

A PK NAIL DRIVEN INTO A SMALL FIR STUMP (CUT LOW TO THE GROUND) IS FOUND TO BEAR N 05° W, 13 3/4 FEET DISTANT FROM THE BELOW MENTIONED FOUND 44 INCH D.B.H. BLACK OAK.

PROPERTY OWNER INDICATED THAT THE ABOVE FOUND PK NAIL AND 44 INCH DBH BLACK OAK MARKED THE LOCATION OF THE CALCULATED NORTH 1/4 CORNER OF SECTION 10 AS SHOWN IN DCSD MAP FILE M106-25

Accessories Found: \_\_\_\_\_

A 44 INCH D.B.H. BLACK OAK, NOTED AS THE ORIGINAL S.E. BEARING TREE FOR THIS CORNER IN A 1988 PROPERTY SURVEY FILED AT THE D.C.S.D. AS M106-25, IS EXAMINED FOR ORIGINAL EVIDENCE. THIS TREE HAS A WELL HEALED SCAR FACING N.N.E. AND A WELL HEALED LOW SCAR FACING E.S.E. THE DEGREE OF HEALING OF THESE SCARS INDICATES THEIR HAVING BEEN MADE IN THE RECENT PAST. WE OPEN THE N.N.E. SCAR AND FIND THAT THIS TREE HAS BEEN PREVIOUSLY OPENED. TREE IS SOUND FROM BARK TO CENTER BUT NO EVIDENCE OF BLAZING OR SCRIBING IS FOUND. A COUNT OF GROWTH RINGS TO THE RECORD 8 INCH DIAMETER DOES NOT VERIFY THIS TREE AS THE O.B.T. WE DO NOT OPEN THE E.S.E SCAR.

SEVERAL OTHER LARGE OAKS NEARBY THE ABOVE MENTIONED TREE HAVE SIMILAR SCARS. WE OPEN THESE TREES AND FIND THEY HAVE ALSO BEEN PREVIOUSLY OPENED AND EXHIBIT NO DISCERNIBLE EVIDENCE OF BLAZES OR SCRIBING.

THERE ARE ALSO ROTTED LARGE OAK STUMPS AND FALLEN TREES IN AREA BUT WE FIND NO COLLATERAL EVIDENCE TO INDICATE THAT ANY OF THESE ARE BEARING TREES.

RENEWAL

Monument Set (Procedure and Description)

NONE NO PERMANENT MONUMENT SET

Monument Detail

New Accessories

N/A

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER LOCATION IS IN REPROD. FOREST. AREA WAS EXTENSIVELY LOGGED EARLY THIS CENTURY. AREA HAS NUMEROUS SKID ROAD EXCAVATIONS.

Comp. Declin. 18 1/2° E

Agency DCSO

Party Chief RW SMITH

Notekeeper Stephen John Flaise

Witnesses S.J. FLAISE

Address

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Larry E. Monrean*

OREGON  
JULY 13, 1979  
LARRY E. MONREAN  
#1830