

GOVERNMENT CORNER RESTORATION FORM

FILED

JK

Township 26S Range 4W Sec. 6 County DOUGLAS

JUL 9 1990

State OR Date 6/26/90 No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

51 | 56

512 | 57

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals (~~#88~~ T26-4) (#97 T26-5)

Monument(s) Found: (Condition and Source)

A 2 1/2" DIA DCSD BRASS CAP ON A 1/4" O.D. IRON PIPE PROTRUDING 14" ABOVE GROUND. BC/IP LEANS 6" NORTH OF PLUMB. (REN#88)

COUNTY SURVEYORS OFFICE
T26S

R 51 | 56 R
5 --- 4
W 512 | 57 W

1964

Accessories Found:

24" NOW 36" DIA. B. OAK IS DOWN SHOWS A PREVIOUSLY OPENED BLAZE, NO SCRIBING VISIBLE. ROOT HOLE BEARS S 65° E, 372.9 FT (REC. S 63° E, 372.9 FT) ORIG. BT

18" NOW 20" DIA W. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS S 50° E, 322.8 FT, (AGREES WITH REC.) REN#88

20" NOW A DOUBLE TRUNKED 2 FT HIGH D. FIR STUMP WITH A 20" EAST AND A 13" WEST TRUNK NO BLAZES OR SCRIBING VISIBLE, BEARS N 81 1/2° E, 320.0 FT (AGREES WITH REC.) REN#88

#125 T26-4 X
#159 T26-5 X

