

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 25 Range 7 Sec. 5 County DOUGLAS

AUG 13 1990

State OREGON Date 7/30/90 No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

531|532
56|55

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #93, #128 T25-7 #107, 151 T24-7

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A 2 1/2 INCH DIAM BRASS CAP
MARKED AS AT RIGHT ON A 1 1/4 INCH
O.D. IRON PIPE IS FIRMLY SET
AND PROTRUDES APPROXIMATELY
10 INCHES FROM A ROUGH LOW MOUND
OF STONE.

T245 R7W

W. C.

1970

531|532
56|55

968

T255 R7W

Accessories Found:

ALL ACCESSORIES FOUND AS NOTED IN RENEWAL 128.
EXCEPT 4" WILLOW BT WHICH IS NOW DEAD.

#161 T24-7 X
#143 T25-7 X

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

N/A

N/A

New Accessories

N/A

Sketch of Monument, Accessories, and General Area

Location & Comments

MONUMENT IS AT BOTTOM OF FILL SLOPE ON WEST SIDE OF COUNTY RD. # 33 AND IS APPROXIMATELY 650 FT. NORTH FROM THE TIE ACCESS BRIDGE (USES RD # 25-7-5.1).

Comp. Declin. 18° E

Agency DCSO

Party Chief STEPHEN JOHN FLAUSE

Notekeeper Stephen John Flause

Witnesses TERRIE FRANSSEN

Address

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Larry E. Monrean

OREGON
JULY 13, 1979
LARRY E. MONREAN
#1830