

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 29S Range 6W Sec. 17 County DOUGLAS

State OR Date 7/16/90 No. \_\_\_\_\_

AUG 13 1990

Corner Designation \_\_\_\_\_

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

S18/S17  
S19/S20

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewals 1958 BLM SURVEY, #235 #265

Monument(s) Found: (Condition and Source)

A 2" DIA ALUM. CAP ON A 5/8" I.R.  
PROTRUDING 15" ABOVE GROUND. (REN #265)

2 1/2" DIA DCSO BRASS CAP ON A 1 1/2"  
IRON PIPE PROTRUDING 6" ABOVE GROUND  
(REN #235) GOES TO CORNER POSITION OF  
1958 BLM SURVEY. BLM RECENTLY  
DESTROYED SCRIBING IN BT'S FROM 1958  
BLM SURVEY, WE AXED OUT SCRIBING IN  
BT'S ESTABLISHED IN REN #235

Accessories Found:

MEASUREMENTS TAKEN FROM 1989 ALUM. CAP/I.R.

6" NOW 28" DIA 2 1/2 FT HIGH OAK STUMP WITH REVERSE ILLEGIBLE  
SCRIBE MARK AND OLD AXE MARKS VISIBLE ON A PREVIOUSLY OPENED  
BLAZE BEARS N 32 1/2° W, 21.8 FT (RECORD N 27 1/2° W, 21.8 FT  
IT IS POSSIBLE WRONG SIDE OF COMPASS READ IN REN #265) ORIG. BT

10" DIA. D. FIR, SCRIBING IS VISIBLE ON AN UNHEALED SINGLE BLAZE  
"S 18 BT" BEARS N 18 3/4° W, 43.6 FT (RECORD N 15° W, 44.4 FT) REN #265

12" DIA. W. FIR, SCRIBING IS VISIBLE ON AN UNHEALED SINGLE BLAZE  
"S 17 BT" BEARS N 46 1/2° E, 42.2 FT (RECORD N 47° E, 42.2 FT)  
REN #265

10" DIA. D. FIR, SCRIBING IS VISIBLE ON AN UNHEALED SINGLE BLAZE  
"S 20 BT" BEARS S 67° E, 26.6 FT (RECORD S 65° E, 26.6 FT) REN #265

10" DIA. I. CEDAR, SCRIBING IS VISIBLE ON AN UNHEALED SINGLE BLAZE  
"S 19 BT" BEARS S 40° W, 71.7 FT (RECORD S 39° W, 72.5 FT) REN #265

1 1/2" IRON PIPE WITH YELLOW PLASTIC CAP BEARS S 88 1/4° W, 81.9 FT  
(AGREES WITH RECORD DETERMINED IN REN #265) FORMERLY DCSO BC/IP  
FROM REN #235

MONUMENT DETAIL

R.I.R. CO.

T29S  
S C  
18/17  
19/20  
1989  
LS 498  
R  
6W  
M

DOUGLAS COUNTY SURVEYORS

S18/S17  
S19/S20  
1977

274

C.S. File No. 64/10-7

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

NONE

BRASS CAP IS SAWED OFF OF 1977 DCSO  
BC/IP A YELLOW PLASTIC CAP IS  
PUT IN CENTER OF IRON PIPE MARKED  
" DOUG. CO. SURVEYOR " I.P. NOW PROTRUDES  
4" ABOVE GROUND.

N/A.

New Accessories

NONE

Sketch of Monument, Accessories, and General Area

Location & Comments

Comp. Declin. 18°E  
Agency DCSO  
Party Chief RANDALL W SMITH  
Notekeeper Randall W Smith  
Witnesses STEPHEN J FLAUSE  
TERRIE FRANSEN

Address

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Larry E. Monrean*

OREGON  
JULY 13, 1979  
LARRY E. MONREAN  
#1830