

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 32S Range 4W Sec. 17 County DOUGLAS

NOV 5 1990

State OR Date 10/30/90 No. _____

Corner Designation

ONLY
1/4 S 17

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals #117, 1971 BLM RESURVEY

Monument(s) Found:	(Condition and Source)
<u>A 3 1/2" DIA. BLM BRASS CAP ON AN IRON PIPE IS FOUND FLUSH WITH GROUND (1971 BLM)</u>	
<u>A DCSO 1 1/2" O.D. FLANGED IRON PIPE IS FOUND INVERTED, PROTRUDING 15" ABOVE GROUND. (FROM REN #117; INVERTED IN 1971 BLM RESURVEY).</u>	
<u>DCSO I.P. BEARS NORTH 0.5 FT FROM BLM BC/IP.</u>	

US DEPT OF THE INTERIOR

T32S R4W

S17

1971

BUR OF LAND MANAGEMENT

Accessories Found:

12" MADRONE W/ROOTHOLE WITH REMAINS OF DECAYED MADRONE ALONG SIDE, NO BLAZES OR SCRIBING VISIBLE, ROOT HOLE BEARS N15°W, 7.3 FT (AGREES WITH RECORD) ORIG. BT

ORIG. SOUTHEAST BT IS GONE.

38" NOW 42" DIA D.FIR WITH A FULLY HEALED SINGLE BLAZE BEARS S59°E, 31.3 FT (AGREES WITH REC) REN #117

35" NOW 35" DIA 2 1/2' HIGH D.FIR STUMP, NO BLAZES OR SCRIBING VISIBLE, BEARS S18 1/2°W, 45.2 FT (AGREES WITH REC) 1971 BLM RESURVEY

#158 X

RENEWAL

Monument Set (Procedure and Description)

NONE

Monument Detail

N/A

New Accessories

28" DIA. 1 1/2 FT HIGH D. FIR STUMP, SET 8" BOAT SPIKE THROUGH BT TAG NEAR TOP CENTER OF STUMP, STAMPED "B01", BOAT SPIKE BEARS S73°E, 68.4 FT.

36" DIA. 4 FT HIGH D. FIR STUMP, SET 8" BOAT SPIKE THROUGH BT TAG NEAR TOP CENTER OF STUMP, STAMPED "B02", BOAT SPIKE BEARS S20°E, 49.0 FT.

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER LIES ON A SOUTHERLY SLOPE IN A NEW CLEAR CUT. APPROX 700 FT NORTH OF GRAVEL RD.

CLEAR CUT



Comp. Declin. 18°E
Agency DCSO
Party Chief RANDALL W SMITH
Notekeeper *Randall W Smith*
Witnesses STEPHEN J. FLAUSE

Address

Surveyor's Seal
REGISTERED
PROFESSIONAL
LAND SURVEYOR

Randall W Smith

OREGON
JULY 25, 1990
RANDALL W. SMITH
2469