

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 30 S Range ZW Sec. 21 County DOUGLAS

State OR Date 2/26/91 No. \_\_\_\_\_

*JK*  
MAR 1 1 1991

Corner Designation

$\frac{1}{4}$  S 21 | S 22

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1909 GLO RETRACEMENT, #144

Monument(s) Found: (Condition and Source)

A 2 1/2" DIA. DCSO BRASS CAP  
ON A 1/4" O.D. IRON PIPE, PROTRUDING  
12" ABOVE GROUND, FROM REN#144

STONE NOT VISIBLE, ON TOP OF  
GROUND, WE DID NOT DIG TO LOOK  
FOR STONE.

COUNTY SURVEYORS OFFICE

T. 30 S R. 2 W

$\frac{1}{4}$  S 21 | S 22

1968

Accessories Found:

16" NOW 23" DIA. 40' HIGH CEDAR SNAG WITH A FULLY HEALED  
SINGLE BLAZE, BEARS N 51° W, 35.6 FT. 1909 GLO

28" NOW 20" DIA. 2 FT HIGH PINE STUMP WITH ROTTED, OPEN  
BLAZES SCRIBING VISIBLE "2" BEARS N 50° E, 19.1 FT  
(RECORD N 52° E, 29.1 FT) 1909 GLO

40" NOW 42" DIA. 4 FT HIGH D. FIR STUMP WITH A PARTIALLY  
HEALED BLAZE, SCRIBING VISIBLE "1/4 S 22 CS BT"  
BEARS S 81 1/2° E, 96.7 FT (REC. S 80° E, 96.7 FT)  
REN # 144

#273 ✓

