GOVERNMENT CORNER RESTORATION FORM

FILED
DEC 2 4 1991
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Township 29S Range 7W Sec. 28 County DOUGLAS

State OR Date 12/18/91 No.

Corner Designation

S29	S28
S32	S33

✓ Condition Report Only
___ Not Found
___ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals 1924 GLO, #52, #66, #126

Monument(s) Found: (Condition and Source)

2½" DIA GLO BRASS CAP ON A 1½" O.D. IRON PIPE PROTRUDING 5" ABOVE GROUND (1924 GLO)

MONUMENT DETAIL

U.S. GENERAL LAND
T 29 S R 7 W

S29	S28
S32	S33

1924

OFFICE SURVEY

Accessories Found:

BT'S FOUND AS NOTED IN LAST RENEWAL (#126)

G.S. File No. 64/21-13 c

RENEWAL

Monument Set (Procedure and Description)

NONE

Monument Detail

N/A

New Accessories

NONE

Sketch of Monument, Acessories, and General Area

Location & Comments

CORNER LIES AT THE INTERSECTION OF A EAST AND SOUTH RUNNING FENCE LINE.

Comp. Declin. 18°E

Agency DCSO

Party Chief RANDALL W SMITH

Notekeeper Randall W Smith

Witnesses STEPHEN J FLAVSE

Address

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Randall W Smith

OREGON
JULY 25, 1990
RANDALL W. SMITH
2469