

Township 21S Range 7W Sec. 10 County DOUGLAS

APR 15 1992

State OREGON Date APRIL 8, 1992 No. \_\_\_\_\_

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation \_\_\_\_\_

10	11
15	14

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 6

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A HAINES "T" IRON (A 1 INCH X 1 INCH ANGLE IRON) WITH A BRASS WASHER (MARKED AS AT RIGHT) IS FIRMLY SET AND PROTRUDES APPROX. 10 INCHES ABOVE GROUND.

WILFORD N. HAINES

#239

Accessories Found:

EVIDENCE OF FOUR BEARING TREES FROM HAINES RENEWAL #6 A RESURVEY OF LINES IN SECTION 10 FILED AS CS 4213.

A 48" FIR NOW A 34 INCH DIAMETER 4 FOOT TALL FIR STUMP WITH A FULLY HEALED DOUBLE BLAZE N 64° W, 115' FEET DISTANT (RECORD N 61° W 117.0 FEET, POSSIBLY A SLOPE DISTANCE)

A 12" CEDAR NOW 26 INCH DBH RED CEDAR WITH A PARTIALLY HEALED DOUBLE BLAZE WITH ILLEGIBLE SCRIBING VISIBLE BEARS S 15° W, 38' FEET DISTANT (RECORD S 17° W, 40' FEET POSSIBLY A SLOPE DISTANCE)

A 40" CEDAR NOW 12 PLUS FOOT TALL BROKEN FIR SNAG WITH A ROTTEN BLAZE FACE WITH NO SCRIBING VISIBLE BEARS N 18 1/4° E 24' FEET DISTANT (RECORD N 22° E, 24' FEET)

A FALLEN BURNED AN BROKEN MAPLE (PROBABLY BT) LIES OUT OF POSITION IN SE QUADRANT FROM MONUMENT.

#1204

C.S. File No. 64/24-120

