

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 21S Range 7W Sec. 10 County DOUGLAS

MAY 15 1992

State OREGON Date APRIL 13, 1992 No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

Corner Designation

SE 1/16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals NONE; ESTABLISHED IN SURVEY M29-67

Monument(s) Found: (Condition and Source)

NA

A "T" IRON WITH A BRASS WASHER
 MARKED "WILFORD N HAINES # 239" FIXED
 TO TOP IS FIRMLY SET AND PROTRUDES
 APPROX. 12 INCHES ABOVE GROUND.

Accessories Found:

BOTH BEARING TREES ARE NOW STUMPS APPROX 2 1/2 TO 3 FEET
 TALL (DIAMS. NOT CHECKED)
 BEARING AND DISTANCE TO NW BEARING TREE (NOW STUMP) CHECKED
 WITH HAND COMPASS AND POCKET TAPE (AGREES REASONABLY WELL WITH
 RECORD). BEARING AND DIST. TO OTHER TREE NOT CHECKED.

