

GOVERNMENT CORNER RESTORATION FORM

FILED

*JS*

Township 19S Range 11N Sec. 36 County LANE

MAY 20 1992

State OR Date 5/7/92

No. \_\_\_\_\_

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation

5/4 S36 ONLY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals M 97-64

Monument(s) Found: (Condition and Source)

BRASS CAP / IRON PIPE

Accessories Found:

11" MAPLE WITH A HEALED BLAZE, BEARING + DISTANCE  
NOT CHECKED (M 97-64)

ALDER BT FROM M 97-64 NOT NOT LOOKED FOR

BC/1P NY451 T20S R11W, BEARS EAST, DIST NOT CHECKED  
(M 97-64)

*C*

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

NONE

N/A

New Accessories

NONE

Sketch of Monument, Accessories, and General Area

Location & Comments

N/A

Comp. Declin. 18°E  
Agency DCSO  
Party Chief RANDALL W. SMITH  
Notekeeper Randall W. Smith  
Witnesses \_\_\_\_\_

Address

Surveyor's Seal  
REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Randall W. Smith*

OREGON  
JULY 25, 1990  
RANDALL W. SMITH  
2462