



Monument Set (Procedure and Description)

Monument Detail

NONE

N/A

NOTE:

SEE RENEWAL #137 MONUMENT IS A SURVEY POINT, UNSURE HOW LOCATION DERIVED.

New Accessories

NORTH WEST CORNER OF TWO CAR GARAGE AT CATHOLIC CHURCH, BEARS N 58 1/2° E 72.5 FT

SOUTH WEST CORNER OF CHAPEL, 0.3 WEST OF DOUBLE DOORS, BEARS N 53 1/4° W, 124.7 FT

POWER POLE "AG 0434" BEARS N 72° W, 20.0 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

MONUMENT IS APPROX. 100 FT SOUTH OF CATHOLIC CHURCH

BT STUMPS TO BE REMOVED FOR CEMETERY EXPANSION

SEE CS FILE # 59/46

Comp. Declin. 18° E  
Agency OCSO  
Party Chief RANDALL W SMITH  
Notekeeper Randall W Smith  
Witnesses STEPHEN T FLAUS

Address

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Randall W. Smith

OREGON  
JULY 25, 1990  
RANDALL W. SMITH  
2469

