

Township 30S Range 9W Sec. 31 County DOUGLASS

State OR Date 9/21/92

No. _____

OCT 6 1992

Corner Designation

S31 | S32
S6 | S5

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

1893 RETRACEMENT

Previous Renewals #33 #91 #126

Monument(s) Found: (Condition and Source)

2 1/2" DIA. DCSO BRASS CAP ON
A 1 1/2" O.D. IRON PIPE PROTRUDING
18" ABOVE GROUND. (REN #91)

SEE REN #126

(STONE) →

14" X 10" X 8" WITH 5 NOTCHES
ON EAST EDGE IS FOUND ON TOP
OF GROUND ALONG WEST EDGE
OF DCSO BC/IP. (1893 RETRACEMENT
SURVEY)

1/4" I.D. IRON PIPE PROTRUDING 18"
ALONG ABOVE GROUND IS FD
ALONG SOUTHEAST EDGE OF DCSO
BC/IP (REN #33)

METAL FENCE POST ALONG SOUTH
EDGE OF BC/IP

Accessories Found:

30" NW 37" DIA 30' HIGH D. FIR SNAG WITH PREVIOUSLY
OPENED BLAZES, NO SCRIBING VISIBLE, BEARS S22°E,
44.5 FT (REC S22°E, 43.2 FT, DIST 1 IS A FACE MEASUREMENT)
1893 BT

3A" NW DECAYED FIR STUMP NO BLAZES OR SCRIBING VISIBLE
BEARS S21 1/2° W, 32.3 FT (AGREES WITH REC) 1893 BT

30" NW 30" DIA. 3 FT HIGH D. FIR STUMP WITH A FULLY
HEALED BLAZE, BEARS N44°E, 42.9 FT (AGREES WITH REC).
1893 BT

8" NW 14" DIA. D. FIR WITH A FULLY HEALED BLAZE, BEARS
S60°W, 34.4 FT. (AGREES WITH REC) REN #33

10" OAK NW 15" DIA. SQUINAPIN WITH A SMALL HEALED
BLAZE 5 FT ABOVE GROUND AND A ROTTED OUT CENTER,
BEARS S51°E, 20.4 FT (AGREES WITH REC) REN #33

COUNTY SURVEYORS OFFICE

T30S R9W

S31 | S32
S6 | S5

T31S
1965

T30R9#147 x
T31R9#174 x C

