

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 25 Range 5W Sec. 10 County DOUGLAS

State OR Date 10-26-92 No. _____

OCT 30 1992

Corner Designation

1/4 S10/S11

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals CS 49/124, M63-32, CS 59/40 (500570)

Monument(s) Found: (Condition and Source)

IRON PIPE & GLASS CAP MONUMENT 1/2 FOOT
BELOW SURFACE.

COUNTY SURVEYORS OFFICE

T 25 S 25 W

1/4 S10/S11

RESET 1977

1960

Accessories Found:

- FIR STUMP 19" (REC. 14") DEARS N 61 1/2° W 27.7 FT. WELL HEALED GLAZE

- 14" NOW 20" W. OAK WITH PARTIALLY HEALED SCAR DEARS N 88° E 49.3 FT
(REC. 49.2 FT)

NO OTHER DT'S FOUND

500570 ✓

C.S. File No. 64/32-11

C

