

GOVERNMENT CORNER RESTORATION FORM

Township 29S Range 8W Sec. 19 County DOUGLAS DEC 14 1992

State OREGON Date NOV 4, 1992

No. _____ COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

S13	S18
S24	S19

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #13 (T29S R9W), #65, #194 (T29 R8)

Monument(s) Found: ⁴⁰92 (Condition and Source)

MONUMENT DETAIL

N/A

ORIGINAL AND STONE MONUMENT FROM RENEWAL #13 ARE NOT FOUND FROM RENEWAL #65 MAGNETIC EVIDENCE INDICATES SET BOATSPIKE IN ASPHALT ROADWAY IS IN PLACE BUT IS NOW BURIED BELOW SURFACE SHALLOWLY.

Accessories Found:

ALL BEARINGS AND DISTANCES MEASURED FROM MONUMENT (ABOVE MENTIONED) NO EVIDENCE OF TWO ROCKS FROM RENEWAL #13 IS FOUND. WEST ROCK WOULD FALL UNDER ROADWAY AND EAST ROCK IS NOT DUG FOR, IN ORDER NOT TO DISTURB BRASS CAP AND IRON PIPE FROM RENEWAL #194.

FROM RENEWAL #65 NO EVIDENCE OF WITNESS CORNER IS FOUND. A 16" OAK NOW A 20 INCH D.B.H. WHITE OAK WITH A FULLY HEALED DOUBLE BLAZE, IN A TIGHT GROUP OF NINE OAKS, NOW ALL FALLEN AND SOON TO BE REMOVED, BEARS S43 1/2° E, 304.8 FEET DISTANT (AS PER RENEWAL #194).

FROM RENEWAL #194 A BRASS CAP/IRON PIPE BEARING OBJECT (ERRONEOUSLY CALLED A WITNESS CORNER), A BEARING TREE, AND A POWER POLE BEARING OBJECT ARE ALL FOUND.

A 2 1/2 INCH DIAMETER BRASS CAP MARKED "DOUGLAS COUNTY SURVEYOR" ON A 1 1/4 INCH O.D. IRON PIPE IS FIRMLY SET PROTRUDING 8 INCHES ABOVE GROUND AND BEARS EAST, 16° FEET DISTANT (AS PER RECORD) (A SURVEY MARKER SIGN BEARS 1 1/2 EAST FROM BC. MON.)

		T29S		
R	S13		S18	R
9				8
W	S24		S19	W
WIT. COR.				
16 FT. WEST TO SEC. COR.				
1981				

A 48" CEDAR NOW A 52 INCH D.B.H. CEDAR WITH A FULLY HEALED SINGLE BLAZE BEARS S88 1/2° W, 498 ± FEET DISTANT (RECORD S89W, 496 ± FT. TO FACE)

A POWER POLE #1C 17 11 BEARS N12 1/4° W, 113 ± FEET DISTANT (RECORD N11 1/2° W, 114.5 FT. PROBABLY TO OLDER POWER POLE FOUND POLE APPEARS NEW).

29-8 # 216 x
29-9 # 101 x

