

GOVERNMENT CORNER RESTORATION FORM

FILED *JF*

Township 27S Range 7W Sec. 31 County DOUGLAS

State OR Date 3-30-93 No. _____

MAY 6 1993

Corner Designation

SOUTH
WIT | COR
1/4 S31 | S32

COUNTY SURVEYOR

DOUGLAS COUNTY, OR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals #29 #60 #79A

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DIA. DCSO BRASS CAP ON
A 1/2" O.D. IRON PIPE PROTRUDING
14" ABOVE GROUND. REN #79A

COUNTY SURVEYORS OFFICE

T 27S R 5W

WIT. COR.

S31 | S32

355' NORTH TO 1/4

1960

Accessories Found:

6" NOW 13" DIA DOUBLE TRUNKED B. OAK WITH A FULLY
HEALED DOUBLE BLAZE ON EAST TRUNK, BEARS N 87° W,
60.1 FT TO ROOT CROWN, CIRC N 87° W 5.4 TO CNT. OF EAST
TRUNK) REN 79A
4" NOW 12" DIA W. OAK WITH A FULLY HEALED DOUBLE
BLAZE BEARS S 4° E, 15.6 FT (CIRC. S 4° E, 15.6 FT)
REN 79A.

