

GOVERNMENT CORNER RESTORATION FORM

FILED

zh

Township 27S Range 6W Sec. 19 County DOUGLAS MAY 12 1993

State OR Date 5-5-93 No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, OR

Corner Designation

1/4 S19 | S20

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1893 BRIGGS, 1960 BYRON

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON A 1 1/2" O.D. IRON PIPE, PROTRUDING 13" ABOVE GROUND (1960 BYRON)

COUNTY SURVEYORS OFFICE
T275

1/4 S19 | S20
R6W
1961

Accessories Found:

24" NOW 36" DIA B. OAK WITH PREVIOUSLY OPENED AND HEALED BLAZES, OPENED BLAZE IS ROTTED NO SCRIBING VISIBLE BEARS N46°E, 17.2 FT (AGREES WITH REC.) 1893 BRIGGS

15" NOW 24" DIA. D. FIR WITH A FULLY HEALED DOUBLE BLAZE, BEARS N85°W, 17.5 FT (AGREES WITH REC.) 1960 BYRON

200390

