

GOVERNMENT CORNER RESTORATION FORM

FILED 8


Township 27S Range 6W Sec. 31 County DOUGLAS

AUG 30 1993

State OR Date 6-15-93 No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals MENSCH 1924

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

3/4" DIA BRASS CAP ON A 3" DIA
IRON PIPE PROTRUDING 10" ABOVE
GROUND.

U. S. GENERAL LAND OFFICE

T 27 S
 R 7 W | R 6 W
 S 36 | S 31

 1924

SURVEY

Accessories Found:

30" NOW 40" DIA B. OAK WITH ROTTEN OUT CENTER, POSSIBLE
BLAZE NO SCRIBING VISIBLE, BEARS N 86° E, 369.6 FT
(ORIG. REC. N 85 1/2° E, 369.6 FT) ORIG. BT

14" NOW 12" DIA 1 FT HIGH OAK STUMP, NO BLAZES OR
SCRIBING VISIBLE, BEARS N 84 1/2° E, 310.2 FT
(AGREES WITH REC) MENSCH 1924

14" NOW 34" DIA B. OAK WITH A FULLY HEALED SINGLE
BLAZE, BEARS N 86 1/4° W, 67.3 FT (AGREES WITH REC)
MENSCH 1924

