

GOVERNMENT CORNER RESTORATION FORM

Date: 9/27/95 By: BC

Township 25S Range 3W Sec. 24 County DOUGLAS Map: _____

This survey consists of:

State OR Date 4-3-95 No. _____

Name: _____

Corner Rpt: 64/63-2

Corner Designation

1/4 S 24

DOUGLAS COUNTY SURVEYOR

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals 1943 GLO

Monument(s) Found: (Condition and Source)

2 1/2" DIA. GLO BRASS CAP ON A
1" O.D. IRON PIPE, PROTRUDES
1 FT ABOVE GROUND (1943 GLO)

U.S. GENERAL LAND OFFICE

1/4 S 24

1943 SURVEY

Accessories Found:

10" NOW 13" DIA. 25 FT HIGH MAPLE SNAG WITH A FULLY
HEALED SINGLE BLAZE, BEARS N 16° W, 12.0 FT (REC N 16° W,
11.2 FT DIST POSSIBLE FACE MEASUREMENT) NEW SPROUTS
GROWING FROM BASE. OBT

16" NOW 24" DIA. 2 FT HIGH CEDAR STUMP, NO BLAZES OR
SCRIBING VISIBLE, BEARS S 48 1/2° E, 17.8 FT (AGREES
WITH REC) OBT

30" NOW 50" DIA 2 FT HIGH D. FIR STUMP NO BLAZES OR
SCRIBING VISIBLE, BEARS S 79 1/2° W, 27.1 FT (AGREES
WITH REC). 1943 GLO

36" NOW 36" DIA. 6 FT HIGH D. FIR STUMP WITH A FULLY
HEALED SINGLE BLAZE, BEARS N 15 1/2° W, 32.3 FT
(AGREES WITH REC) 1943 GLO

