

GOVERNMENT CORNER RESTORATION FORM

Date: 9-17-97 By: RE

Township 25S Range 4W Sec. 19 County DOUGLASS Map:

This survey consists of:

State OR Date 8-14-97 No. \_\_\_\_\_

Narrative: \_\_\_\_\_  
Corner Rpt: CS 64/75-35

Corner Designation INT L  
SE  
DLC 50

- DOUGLAS COUNTY SURVEYOR ONLY
- Condition Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1983 M 94-1

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

5/8" IRON ROD FLUSH WITH GROUND (1983)

N/A

Accessories Found:

NO OBJ'S FOUND

36" NOW 39" DIA B. OAK WITH A FULLY HEALED SINGLE BLAZE BEARS N21 1/2° E, 117.4 FT (REC N22 1/2° E, 116.0 FT DIST'S TO FACE) 1983

37" NOW 35" DIA DEAD AND ROTTED STANDING OAK NO SCRIBING OR BLAZES VISIBLE, BEARS S26° E, 70.3 FT (REC S26° E, 69.1 FT) 1983

Monument Set (Procedure and Description)

Monument Detail

NONE

N/A

New Accessories

11" DIA. W. OAK DOUBLE BLAZED AND SCRIBED "SE DLC 50 CS BT"  
BEARS S 16° E, 101.3 FT

27" DIA. W. OAK SINGLE BLAZED AND SCRIBED "SE DLC 50 CS BT"  
BEARS S 18° W, 349.4 FT

36" DIA. W. OAK DOUBLE BLAZED AND SCRIBED "SE DLC 50 CS BT"  
BEARS N 78° E 280.4 FT  
Sketch of Monument, Accessories, and General Area

Location & Comments

Comp. Declin. 17 3/4° E  
Agency DCSO  
Party Chief RANDALL W. SMITH  
Notekeeper  
Witnesses STEPHEN J. FLAISE

Address

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Randall W. Smith*  
JULY 25, 1990  
RANDALL W. SMITH  
2469

