

GOVERNMENT CORNER RESTORATION FORM

Date: 9-23-97 By: JP

Township 25S Range 5W Sec. 26 County DOUGLAS

This survey consists of:

State OREGON Date AUG 26, 1997 No. _____

Map: _____

Narrative: _____

Corner Rpt: C.S. 64/75-38

Corner Designation

C 1/4

S26

DOUGLAS COUNTY SURVEYOR

- Condition Report Only _____
- Not Found _____
- Renewed _____
- Unrecorded _____
- Surveyed In _____
- Referenced Out _____

Previous Renewals NONE

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A 2 1/2 INCH DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON A 1 1/2 INCH O.D. IRON PIPE FIRMLY SET AND PROTRUDING APPROXIMATELY 5 INCHES ABOVE GROUND.

COUNTY SURVEYORS OFFICE

T25S R5W

C 1/4

S26

1973

Accessories Found:

TWO ORIGINAL BEARING TREES FOUND. A 14 INCH OAK NOW AN 18 INCH D.B.H. BLACK OAK WITH A FULLY HEALED DOUBLE BLAZE BEARS S 71 1/2° E, 224.4 FEET DISTANT (RECORD S 75° E 224.4 FT.).
A 30 INCH ASH NOW A 39 INCH D.B.H. ASH WITH A FULLY HEALED DOUBLE BLAZE BEARS N 12° W, 328.7 FEET DISTANT (RECORD N 11° W 328.7 FT.).
A 5/8 INCH DIAMETER IRON ROD FIRMLY SET PROTRUDING 3 INCHES BEARS N 20° W, 356 FEET DISTANT (AS PER RECORD SEE DOUGLAS COUNTY SURVEY RECORDS RM 2-54). THIS IRON ROD LIES APPROXIMATELY 1 FOOT SOUTH FROM CORNER POST OF FENCES RUNNING NORTHERLY AND WESTERLY.

