

GOVERNMENT CORNER RESTORATION FORM

Date: 12-15-97 By: PC

Township 27S Range 1W Sec. 27 County DOUGLAS

This survey consists of:

State OR Date 12-8-97 No. _____

Map: _____
Narrative: _____
Corner Rpt: CS 04/78-35

Corner Designation

1/4 S28/S27

DOUGLAS COUNTY

Condition: Surveyed Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals # 95 1969 DCSO

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON A
1 1/2" OD IRON PIPE PROTRUDES
14" ABOVE A MOUND OF
STONE (1968)

COUNTY SURVEYORS OFFICE

T27S R1W

1/4 S28/S27

1969

Accessories Found:

18" NOW 35" DIA. D. FIR WITH A FULLY HEALED
DOUBLE BLAZE (NOTE: BURNT BARK TREE
IS ALIVE) BEARS S60°E, 31.7 FT (AGGIES
WITH REG.) OBT
14" NOW 19" DIA. CEDAR WITH A FULLY HEALED
SINGLE BLAZE (NOTE: BURNT BARK TREE IS
ALIVE) BEARS S85°W, 7.9 FT (AGGIES
WITH REG.) OBT

