

GOVERNMENT CORNER RESTORATION FORM

Date: 2/17/98 By: JC

Township 255 Range 6W Sec. 6

County DOUGLAS

This survey consists of:

State OR Date 2-11-98

No. _____

Narrative: _____

Corner Rpt: 64/79-30

Corner Designation

$\frac{1}{4} \frac{S6}{S7}$

DOUGLAS COUNTY

Condition RENEW Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1923 SPRINGER, 1963 DC50

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A 1 1/2" OD
IRON PIPE PROTRUDES 1 1/4"
OUT OF HOLLOWED OUT 1 FT
HIGH 60" DIA CEDAR STUMP.
(1963 BC/1P AND ORIG. CORNER TREE)

COUNTY SURVEYORS OFFICE
T 255

$\frac{1}{4} \frac{S6}{S7}$
RW
1963

Accessories Found:

NO OBT'S FD
NO BT'S FROM 1923 FD

6" NOW 17" DIA. D. FIR WITH A FULLY HEALED DOUBLE
BLAZE, BEARS N55°E, 7.0 FT (AGREES WITH REC.) 1963

14" NOW 20" DIA. J. CEDAR WITH A FULLY HEALED DOUBLE
BLAZE, BEARS S79°W, 39.6 FT (AGREES WITH REC.) 1963

Monument Set (Procedure and Description)

Monument Detail

NONE

N/A

New Accessories

9" DIA. G. FIR, DOUBLE BLAZED AND SCRIBED "Y4S6CSBT"
BEARS N88°E, 24.0 FT

10" DIA. D. FIR, DOUBLE BLAZED AND SCRIBED "Y4S7CSBT"
BEARS S9 1/2°W, 9.2 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER LIES AT THE INTERSECTION OF FENCES WITH OLD DOWN FENCE WIRE RUNNING SOUTH AND WEST AND NEW FENCE RUNNING EASTWESTLY.

Comp. Declin. 17 3/4° E
Agency DCSO
Party Chief RANDALL W. SMITH
Notekeeper [Signature]
Witnesses STEPHEN J. FLAISE

Address

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature] EXPIRES 6-30-98

OREGON JULY 25, 1990 RANDALL W. SMITH 2469

