

GOVERNMENT CORNER RESTORATION FORM

Date: 3-3-1998 By: JC

Township 255 Range 6W Sec. 18

County DOUGLAS This survey consists of: _____

State OR Date 2-26-98 No. _____

Narrative: _____

Corner Designation

S13	S18
S24	S19

Corner Rpt: 64/79-36

DOUGLAS COUNTY SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1968 BLM

Monument(s) Found: (Condition and Source)

3 1/2" DIA BRASS CAPON A 2 1/2"
OLD IRON PIPE, PROTRUDES
8" ABOVE GROUND, 1967

U.S. DEPT. OF THE INTERIOR

T255	
RTW	RGW
S13	S18
S24	S19

1968

BUR. OF LAND MANAGEMENT

Accessories Found:

38" NOW 38" DIA D.MAD MARROCK WITH A PARTIALLY
HEALED SINGLE BLAZE, SCRIBING VISIBLE, 255
RGW S18 BT, BEARS N49°E, 88.4 FT
(AGREES WITH REC.) 1968

13" NOW 18" DIA. D. FIR WITH A FULLY HEALED SINGLE
BLAZE (REC. S52°E, 125.4 FT) DISTANCE NOT
CHECKED HILLSIDE STEEP AND FULL OF BRUSH
BRG. LOOKS GOOD. 1968

17" NOW 30" DIA. 2 FT HIGH D. FIR STUMP WITH
A FULLY HEALED BLAZE, BEARS N54°W, 62.7 FT
(AGREES WITH REC.) 1968

1968 SW BT NOW GONE,

Monument Set (Procedure and Description)

Monument Detail

NONE

N/A

New Accessories

7" DIA. D.F. FIR DOUBLE BLAZED AND SCRIBED "T Z S S R 6 W S I 8 C S B T"
BEARS N 42° E, 12.2 FT

4" DIA. D.F. FIR DOUBLE BLAZED AND SCRIBED "X C S B T"
BEARS N 65° E, 14.8 FT

CENTER OF CONCRETE BRIDGE OVER UMPQUA RIVER
BEARS S 50° W APPROX 1 1/2 MILES
Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER LIES AT THE
INTERSECTION OF FENCE
LINE WITH FENCES
RUNNING SOUTH, NORTH
AND EAST

NO TREES WEST OF
CORNER

Comp. Declin. 173° 40' E
Agency DCSO
Party Chief RANDALL SMITH
Notekeeper [Signature]
Witnesses STEPHEN FLAISE

Address

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Randall W. Smith
EXPIRES 6-30-98

OREGON
JULY 26, 1990
RANDALL W. SMITH
2409

