

GOVERNMENT CORNER RESTORATION FORM

Date: 11-6-96 By: JP

This survey consists of:

Township 31 S Range 7 W Sec. 26 County DOUGLAS

Map: _____

State OR Date 9-5-96 No. _____

Narrative: _____

Corner Rpt: CS. 65/9-9

Corner Designation

1/4 S27 | S26

DOUGLAS COUNTY SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

P1# 200240

Previous Renewals 1962 JOHNSTONE, 1964 BLM 1989 JOHNSTONE MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

3/4" DIA. BRASS CAP ON A 2 1/2" O.P. IRON PIPE PROTRUS 12" ABOVE GROUND (1964 BLM.)

U.S. CADASTRAL SURVEY
T31S R7W

1" I.D. IRON PIPE PROTRUS 14" ABOVE GROUND FOUND ALONG WEST EDGE OF EC/IP. (1962)

1/4 S27 | S26

1964

ABOVE MONUMENTS RESET BY HOWARD JOHNSTONE IN 1989

BUREAU OF LAND MANAGEMENT

Accessories Found:

26" DIA. PINE NOW ROOT HOLE BEARS S 12° W, 21 1/2 FT (AGREES WITH 1964 BLM REC.) OBT

ORIG. NE BT NOW GONE

24" NOW 33" DIA. DIE IR WITH A FULLY HEALED DOUBLE BLAZE, BEARS N 2 1/2° W, 21.0 FT (AGREES WITH 1962 AND 1989 JOHNSTONE REC.) 1962 JOHNSTONE

1962 JOHNSTONE SE BT NOW GONE

2" NOW 9" DIA. CHAINLAMP WITH AN OPEN DOUBLE BLAZE, SCRIBING VISIBLE "1/4 S27 BT" BEARS S 10° W, 38.4 FT (AGREES WITH REC.) 1989 JOHNSTONE

