

GOVERNMENT CORNER RESTORATION FORM

Date: 11-15-96 By: JP

This survey consists of:

Township 245 Range 1W Sec. 187 County DOUGLAS

Map: \_\_\_\_\_

State OR Date 10-28-96 No. \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Mpt: C.S. 65/9-21

Corner Designation

DOUGLAS COUNTY SURVEYOR

1/4 S 27  
534

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals #30

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAPON A 1 1/2" O.D.  
IRON PIPE PROTRUS 12"  
ABOVE GROUND (C# 76)

F D A 15" X 11" X 8" STONE  
MARKED "1/4" 4 FT DOWN HILL  
SOUTHEASTERLY OF BC/1P  
OUT OF GROUND.

COUNTY SURVEYORS OFFICE

T 245

S 27

1/4 534

R 1W

1962

Accessories Found:

10" NAW 2 1/2" DIA ROTTEN 2 FT HIGH O. FIRE STUMP WITH  
A HEALED BLAZE BEARS N 46° E, 1016 FT (AGREED  
WITH ORIG. REC.) OBT

ORIG. SE BT NOT FOUND

RENEWAL

Monument Detail

Monument Set (Procedure and Description)

ORIG STONE IS PLACED ALONG  
SOUTHERLY EDGE OF BC/IP

N/A

New Accessories

- 6" DIA D. FIR DOUBLE BLAZED AND SCRIBED "1/4 S 34 CS BT" BEARS S 32 1/2° W, 30.2 FT
- 9" DIA. HEMLOCK DOUBLE BLAZED AND SCRIBED "1/4 S 34 CS BT" BEARS S 26° E, 35.2 FT.
- 3" DIA D. FIR DOUBLE BLAZE SCRIBED "BT" BEARS N 50° E 17.9 FT
- 6" DIA. CHINQUAPIN DOUBLE BLAZED AND SCRIBED "1/4 S 27 CS BT" BEARS N 70 1/2° W, 28.3 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER LIES ON A STEEP  
SOUTHEASTERLY SLOPE

Comp. Declin. 17 3/4° E  
 Agency DCSO  
 Party Chief RANDALL W. SMITH  
 Notekeeper [Signature]  
 Witnesses STEPHEN J. FRANCE

Address

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

[Signature]  
EXPIRES 6-30-98

OREGON  
JULY 25, 1990  
RANDALL W. SMITH  
2489

