

GOVERNMENT CORNER RESTORATION FORM

Date: 11-18-96 By: JP

Township 24S Range 1W Sec. 28

County DOUGLAS This survey consists of:

State OR Date 10-31-96 No. _____

Map: _____

Narrative: _____

Corner Rpt: C.S. 65/9-26

Corner Designation

S29	S28
S32	S33

DOUGLAS COUNTY
 Condition: Surveyed Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals #2 #104 #144

Monument(s) Found: (Condition and Source)

3" DIA. DRILL CAP SET IN ROCK ON
A CUT BANK 6" BELOW GROUND
ON A ROAD CUT BANK. (#144)

2 1/2" DIA. BRASS CAP ON A 1 1/2" D.I.D.
IRON PIPE PROTRUDES 6" ABOVE
GROUND IN ROAD SHOULDER (#104)
(NOTE THIS COR. IS A BEARING OBJECT AS
LINE WAS NOT RUN BETWEEN SEC. IS IN REN 104)
FROM WIT. COR (BC/IP) CORNER (DRILL
CAP) BEARS N 89° E, 60.0 FT
(AGREES WITH RECORD PER REN #144)

DOUGLAS CO SURVEYORS OFFICE
T24S

29	28
32	33

RIW

1983

COUNTY SURVEYORS OFFICE
T24S

WIT. COR.

S29	S28
S32	S33

 TO COR.
 60 FT. E.
 RIW
 1970

Accessories Found:

- BT'S TO WIT. COR (BC/IP)
- 10" NOW 9" DIA 3 FT HIGH PARTIALLY BURIED ROTTED PINE
STUMP, NO SCRIBING VISIBLE, BEARS N 76° W, 14.5 FT
(AGREES WITH REN #144) REN #104
- 11" NOW 12" DIA 6 FT HIGH ROTTED P. FIR SNAG WITH AN
UNHEALED SINGLE BLAZE, SCRIBING VISIBLE "WC T24S RIW S29
CS BT" BEARS N 37° E, 30.3 FT (REC PER REN #104 N 37° E
31.4 FT DIST GOES TO CENTER OF TRUNK.) REN #104
- BT'S TO SEC. COR. (DRILL CAP)

6" NOW 13" DIA 1 1/2 FT HIGH ROTTED PINE STUMP WITH
SCRIBING VISIBLE "T" BEARS S 28 1/2° E, 16.5 FT
(AGREES WITH REC.) ORT

18" DIA 2 FT HIGH D. FIR WITH BOAT SPIKE IN TOP,
BS BEARS S 76° E, 35.4 FT (AGREES WITH BT-TAG,
REC PER REN #144 S 76° E 34.5 FT) REN #144

ALL OTHER BT'S NOW GONE

