

Date: 12-16-96 By: JP

GOVERNMENT CORNER RESTORATION FORM

This survey consists of:

Township 25S Range 2E Sec. 29 County DOUGLAS

Map: _____

State OR Date 11-6-96 No. _____

Narrative: _____

Corner Rpt: C.S. 65/9-32

Corner Designation

1/4 S30/S29

DOUGLAS COUNTY SURVEYOR

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals N/A

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAPON A 1"
O.D. IRON PIPE PROTRUDES 11"
ABOVE GROUND (ORIG. COR.)

U.S. GENERAL LAND

1/4

S30/S29

1928

OFFICE SURVEY

Accessories Found:

14" NOW 26" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE,
BEARS N82°E, 6.0 FT (REC. N82°E, 7.9 FT DIST
FITS WELL WITH A SLOPE MEASUREMENT) OBT

10" NOW 11" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE,
BEARS N28°W, 10.6 FT (REC. N32°W, 10.6 FT BRG
POSSIBLY READ ON WRONG SIDE OF COMPASS) OBT

